CLEAR AID AC

POTABLE WATER QUALITY COAGULANT

MAY CAUSE SKIN AND EYE IRRITATION

READ LABEL AND MSDS PRIOR TO USE
Contact your Meras representative for directions and proper use instructions

D.O.T. and Hazard Information: Non-regulated Material, Liquid Contains no hazardous ingredients.

NET CONTENTS: 55 GAL.

FIRST AID:

IF IN EYES: Hold eye open and rinse slowly and gently with water for 15-20 minutes. Remove contact lenses, if present, after first 5 minutes, then continue rinsing eye. Call poison control center or doctor for treatment advice, if necessary.

IF ON SKIN OR CLOTHING: Take off contaminated clothing. Rinse skin immediately with plenty of water for 15-20 minutes. **IF SWALLOWED:** Call poison control center or doctor for treatment advice. Have person sip a glass of water if able to swallow. Do not induct vomiting unless told to do so by the poison control center or doctor. Do not give anything by mouth to an unconscious person. **IF INHALED:** Move person to fresh air.

STORAGE AND DISPOSAL:

STORAGE: Keep product dry in tightly closed original container when not in use. Store in a cool, dry, well-ventilated area. Product should be stored at 50° F or above.

DISPOSAL: Wastes resulting from the use of this product may be disposed of on site or at an approved waste disposal facility. DO NOT REUSE EMPTY CONTAINER. Triple rinse the container (or equivalent). Then offer for recycling or reconditioning, or puncture and dispose of in a sanitary landfill, or incinerate.

KEEP OUT OF THE REACH OF CHILDREN. FOR INDUSTRIAL USE ONLY

HMIS RATINGS:

| HEALTH | 1 |
|---------------------|---|
| FLAMMABILITY | 0 |
| REACTIVITY | 0 |
| PERSONAL PROTECTION | В |

HMIS HAZARD EXPOSURE RATING:

0=Minimal; 1=Slight; 2=Moderate; 3= High; 4=Extreme

PERSONAL PROTECTION GUIDE:

- A = Safety Glasses
- B = Safety Glasses & Gloves
- C = Safety Glasses, Gloves, Protective Suit & Boots
- D = Gloves, Protective Suit & Boots, & Face Shield
- E = Safety Glasses, Gloves & Dust Mask
- F = Safety Glasses, Gloves, Protective Suit & Boots & Dust Mask
- G = Safety Glasses or Face Shield, Gloves & Vapor Respirator
- H = Safety Glasses, Gloves, Protective Suit & Boots, & Vapor Respirator
- X = Special Equipment



2401 E ORANGEBURG AVE # 675 MODESTO, CA 95355 415-240-4918

TRANSPORTATION EMERGENCY NUMBER: 1-800-424-9300

245-QA08