

MERAS 6112

Thermal Process

WARNING

HAZARD STATEMENTS: CAUSES SERIOUS EYE IRRITATION. CAUSES SKIN IRRITATION. SUSPECTED OF CAUSING CANCER.

READ LABEL AND SDS PRIOR TO USE

Contact your Meras representative for directions and proper use instructions

D.O.T. and Hazard Information: Contains no hazardous ingredients.

NET CONTENTS: 55 GAL.

PRECAUTIONARY STATEMENTS:

Wash hands thoroughly after handling
Wear protective gloves/protective clothing/eye protection/face protection.
Obtain special instructions before use

Do not handle until all safety precautions have been read and understood

IF ON SKIN: Wash with soap and water.

IF SKIN IRRITATION OCCURS: Get medical advice/attention.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do. Continue rinsing.

IF EYE IRRITATION PERSISTS: Get medical advice/attention.

IF exposed or concerned: Get medical advice/attention

STORAGE AND DISPOSAL:

STORAGE: Keep product dry in tightly closed original container when not in use. Store in a cool, dry, well-ventilated area. Product should be stored at 50° F or above.

DISPOSAL: Wastes resulting from the use of this product may be disposed of on site or at an approved waste disposal facility. DO NOT REUSE EMPTY CONTAINER. Triple rinse the container (or equivalent). Then offer for recycling or reconditioning, or puncture and dispose of in a sanitary landfill, or incinerate.

KEEP OUT OF THE REACH OF CHILDREN. FOR INDUSTRIAL USE ONLY

HMIS RATINGS:

HEALTH	2
FLAMMABILITY	0
REACTIVITY	0
PERSONAL PROTECTION	B

HMIS HAZARD EXPOSURE RATING:

0=Minimal; 1=Slight; 2=Moderate; 3= High;
4=Extreme

PERSONAL PROTECTION GUIDE:

A = Safety Glasses

B = Safety Glasses & Gloves

C = Safety Glasses, Gloves, Protective Suit & Boots

D = Gloves, Protective Suit & Boots, & Face Shield

E = Safety Glasses, Gloves & Dust Mask

F = Safety Glasses, Gloves, Protective Suit & Boots & Dust Mask

G = Safety Glasses or Face Shield, Gloves & Vapor Respirator

H = Safety Glasses, Gloves, Protective Suit & Boots, & Vapor Respirator



2401 e orangeburg ave # 675

Modesto, 95355

1-866-899-9762

TRANSPORTATION Emergency

Number: 1-800-424-9300

6112-QA08