



MERAS™

ENGINEERING

601 VAN NESS AVE #E3-725, SAN FRANCISCO, CA 94102
866.899.9762

Well Blast


PRINCIPLE USE: Cleaning and Descaling of Wells

CONTAINS: Glycolic Acid

DANGER: **H314** Causes severe skin burns and eye damage. **H302** Harmful if swallowed. **P260** Do not breathe dust/fume/gas/mist/vapors/spray. **P220** Keep away from metals. **P303+P361+P353** IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. **P305+P351+P338** IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. **P405** Store locked up. **P501** Dispose of contents/container in accordance with local/regional/national/international regulations.

D.O.T. & HAZARD INFORMATION:

UN3265, Corrosive liquid, acidic, organic, n.o.s. (Glycolic Acid), 8, II



Degree of Hazard

4 = EXTREME
3 = HIGH
2 = MODERATE
1 = SLIGHT
0 = INSIGNIFICANT

HEALTH	3
FIRE	0
REACTIVITY	0

PERSONAL PROTECTION: C

KEEP OUT OF THE REACH OF CHILDREN

EMERGENCY CONTACT:
ChemTrec 800-424-9300 (14228)

SEE SAFETY DATA SHEET FOR ADDITIONAL INFORMATION